

Thursday, July 15, 2021

## Wisepill RT2000

### **Version 2.5.4**

- Fixed a buffer overflow condition that could cause data corruption in event messages in rare cases.

### **Version 2.5.3**

- A change was made to prevent the LEDs from flashing during a heartbeat event.

### **Version 2.5.2**

- The time required by the modem to start up was increased.

### **Version 2.5.1**

- Fixed a case where the GSM modem is not powered down. This could happen in the unlikely case where the modem fails to start up after three attempts.

### **Version 2.5.0**

- A Hardware Watchdog timer was activated which will reset the device if the device enters an inactive state for an extended period of time.

### **Version 2.4.6**

- A Software Watchdog timer was implemented to limit every device session to 10 minutes (maximum).
- A change was made to prevent the device from writing to the log file if the battery is very low battery (3.3V) .

### **Version 2.4.0**

- The firmware was upgraded to support the Telit LTE (4G) modem